



Sun Odyssey 24.2 - 1997

<https://www.yachtadvert.com/fr/1755-jeanneau-sun-odyssey-24.2.html>

11 460 â,- ttc



Général

Constructeur : Jeanneau
Matériau : GRP Poly
Largeur : 2,44 m
Radeau : Non
Leasing en cours : Non

Sous type : Plaisance
Année : 1997
Longueur : 7,01 m
Quille : Quille ailette
Région : Chichester Marina, Royaume-Uni

Moteurs

Nombre : 1

Marque moteur : Suzuki DF 15 ALT
Puiss. Unit. (CV) : 15

Aménagements

Flybridge : Non

Timonerie : Non

électronique

Pilote auto : Non

GPS : Non

VHF : Non

Déssalinisateur : Non

Radar : Non

Sondeur : Non

Traceur de carte : Non

Convertisseur 12/220 : Non

équipement de pont

Hydraulique : Non

Plateforme AR : Non

Taud d'hivernage : Non

Capote de roof : Non

Cockpit en teck : Non

Grand voile sur enrouleur : Non

Passerelle : Non

Bossoirs : Non

Guindeau électrique : Non

Taud cockpit : Non

Pont teck : Non

Génois sur enrouleur : Non

Spinnaker : Non

équipements principaux

Propulseur Arrière : Non

Clim. : Non

Eaux noires : Non

Annexe : Non

Propulseur avant : Non

Groupe élec. : Non

Eau chaude : Non

Flaps : Non

Moteur annexe : Non

électroménager

Congélateur : Non	Glaçons : Non
Micro-ondes : Non	Four : Non
Réchaud électrique : Non	Réchaud gaz : Non
Lave-linge : Non	Chauffage : Non
Antenne TV : Non	Lave-vaisselle : Non
TV SAT : Non	TV : Non

Divers

Remarks :

"Rhubarb" is a nicely presented and well equipped example of this well-renowned cruiser. 1997 built, this Jeanneau Sun Odyssey 24.2 is in good condition, well equipped, ready to sail & cruise. Perfectly located within Chichester Harbour. Full paper history, going back to original purchase with evidence of VAT paid.

This fin keeled, outboard motor version of the Sun Odyssey 24.2 is extremely spacious for its length. With a genuine double berth aft, two forward berths, a practical galley layout with twin hob cooker, and a toilet equipped washroom (sink inoperative). A spacious cockpit, with free access to the stern swim platform and ladder.

A host of recent upgrades including new running & standing rigging (2021), totally new mast routed electronics, full epoxy barrier coat on the hull under the waterline (4/5 coats, July 2020), new furling system (2023) and new engine (Suzuki 15HP direct injection 2024) amongst many other improvements & new items.

She has been well looked after and cared for over the years, with one previous owner even owning her multiple times! Rhubarb has proudly featured on the cover the May 2014 issue of Practical Boat Owner (PBO magazine) as their second-hand boat test. She received a glowing report as both a fantastic model for safe and fun sailing on a budget, as well as being a lovely example of the popular pocket cruiser.

Owners Comments

Rhubarb is a much loved and cared for boat, which has given a great deal of freedom and enjoyment during the past 4 years. I have exclusively sailed her throughout the Solent, going on various day trips, and longer excursions. Previous owners have taken her as far as the West Country. I have found there is space to comfortably sleep 3 adults onboard, though previous owners have slept up to 5 people (2 adults, 3 children).

Please call us on 01243 550042 to arrange a viewing.

Accommodation :

Sleeps 4 adults comfortably

Forward V-berth

Aft double berth under cockpit

Saloon with settees

Compact galley: sink, two-burner stove

Heads compartment with marine toilet & sink

Inventory :

ELECTRONICS

• All new mast routed cables (New Oct 2021)

• Masthead wind unit (New Oct 2021)

• Whipflex stainless steel whip antenna (New Oct 2021)

• Masthead Hella trilight, LED compatible (New Oct 2021)

• Mast Steaming Light (New Oct 2021)

• NASA Marine Target 2 Depth

• Clipper electronic compass

• Nasa Marine Target Speed & Distance log (inoperative but replacement fitted at chart table)

• Clipper Wind unit

• 2 x 12V well-functioning batteries (1 new Sep 2025), charged via outboard motor & stern mounted wind generator (Dolphin Ampair)

• ICOM IC-M330GE (New 2021) fixed DSC VHF Radio

• Lowrance HDS-5M cockpit mounted chart plotter

• Cabin lighting

• Electronic bilge pump

• USB charging port</p><p>

EQUIPMENT

• Raymarine ST 1000+ tiller autopilot

• QCR Anchor (I estimate approx. 10kg weight) with 25m galvanised chain spliced onto 30m rope

• 8 Fenders

• Plenty of mooring lines & spare lengths of rope

• 2x cockpit seat cushions

• Box full of spare blocks, shackles, pins, 316/A4 Steel bolts etc.

• Basic tool box

SAFETY

• Manual bilge pump located in the cockpit, pump handle stowage in cockpit locker.

• Electric bilge pump

• Horseshoe buoy

• 18-inch folding radar reflector

• 2x 1kg Dry powder fire extinguishers (2021)

• Fire blanket

• Black signal cone & signal ball

• Set of wooden bungs

• Flexible plastic bailer</p><p> </p>

Mechanical :

ENGINE

2024 Suzuki long shaft 15 4 stroke outboard with power tilt mechanism.

Cockpit throttle control and electric start.

ABOVE DECK

New standing rigging, incl. rigging screws & mast base assembly (2021). Riggers inspection found mast, spreaders etc to be in good condition.

Entirely new running rigging (May 2021), colour coded, every line Liros Herkules braid on braid polyester

Transom hung rudder with tiller steering

Fractional sloop rig

Slab reefing mainsail with lazyjacks and boom packing system

Furling genoa

Sail storage bags in good condition

Spinnaker halyard, though no spinnaker sail

Two Harken standard non-tailing winches (Cleaned and re-greased Aug 2021), with 2 winch handles (tube of Harken winch grease spare)

Masthead wind unit (new Oct 2021)

Removable 25L fuel tank in secure position within cockpit locker (vents overboard)

Campingaz 907 (2.72kg) butane bottle, & bottle cradle located in cockpit locker (vents overboard)

HULL AND UNDER WATERLINE

2020 - Stripped back to original bare gelcoat, found to be in brilliant condition, suspected to have been first time stripped back to original gelcoat layer. Minor fiberglass repairs to a few areas where there were superficial gelcoat cracks (though needed grinding out to investigate), then given 4 alternating grey/green (in some areas 5) layers of International Gelshield 200 epoxy barrier coat.

Keel to hull fillet joint re-sealed with West System G-Flex 655-K - although found to also be in very good condition, no areas of rust or water intrusion - it was decided to preventatively re-do the fillet joint to ensure continued seal for years to come.

























